OUT62977

5X1

5X1 <u>S E C R E T</u>

300009Z

CITE

1967 AUG 30 00 26**Z**

1. CAMERA B-7 WAS USED ON MISSION G-977 FLOWN 26 AUGUST 1967. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.


2. ORIGINAL NEGATIVE:

A. DENSITY AND RESOLUTION ARE GOOD.

- B. 9R SIDE: ROLLER CHATTER AND ASSOCIATED PLUS DENSITY OVALS ARE PRESENT ON BOTH THE INBOARD AND OUTBOARD EDGES THROUGHOUT. FAINT LONGITUDINAL PLUS AND MINUS DENSITY STREAKS ARE PRESENT THROUGHOUT THE MISSION. FRAMES 627, 628, AND 629 CONTAIN A HEAVY LONGITUDINAL PLUS DENSITY STREAK. FRAME 870 CONTAINS A GROUP OF SMALL PLUS DENSITY DOTS. FRAME 1423 CONTAINS FOG EXTENDING 2.0 INCHES DIAGONALLY FROM THE OUTBOARD EDGE. HEAT SPLICES ARE PRESENT IN FRAME 868 AND BETWEEN FRAMES 1260/1261 AND 1583/1584.
- C. 9L SIDE: EDGE STATIC AND ROLLER CHATTER ARE PRESENT ON BOTH EDGES OF THE FILM THROUGHOUT. THE OUTBOARD EDGE FIDUCIALS ARE PARTIALLY OBSTRUCTED ON ALL FRAMES. A PREPROCESSING HEAT SPLICE IS PRESENT IN FRAME 836. A HEAT SPLICE IS ALSO PRESENT BETWEEN FRAMES 899 AND 900. SMALL EMULSION GOUGES AND PINHOLES ARE PRESENT INTERMITTENTLY.
- D. BOTH SIDES: THE DATA BLOCK MISSION NUMBER IS INCORRECT. THE LAST TITLED FRAME IS 1592. MODE 5 OF CAMERA OPERATION WAS UTILIZED THROUGHOUT. CYCLE RATE IS 4.5 SECONDS AND OVERLAP BETWEEN VERTICAL FRAMES IS APPROXIMATELY 60 PERCENT.
 - 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE APPROXIMATELY 30 PERCENT OF THE MISSION. **GP-1**

SECRET

END OF MESSAGE



NGA review(s) completed.

